



**2005-2007 Cobalt/Pursuit/G5**  
**Front Airbag Non-Deployment**  
**709,741 Vehicles**  
**Cost Estimate: \$14.2M-\$37.7M**

ETQ N-130454

**Locations: US, CAN, MEX**

**Condition:**

Front airbag non-deployment has been identified in certain crash events. In those events the ignition switch was in ACCESSORY or OFF.

**Root Cause:**

- Field incidents involve vehicles going off the road or hitting smaller objects shortly before a more significant impact.
- The driver's knee may be interacting with the keys (ignition cylinder location).
- The mass of the keys may be causing the ignition switch to rotate and the torque to rotate may be below specifications.

**Effects:** The airbags will not deploy if the ignition is not in RUN.

**Number of Reports:**

23 allegations of front airbag nondeployment. 28 VOQs for "Ignition Off" while driving.

**Service Bulletin:** Bulletin #05-2-35-007 – Inadvertent key turning – issued Oct 2005.

**Ignition Switch Change:** Increased effort for RUN to ACCESSORY.

**Rate & Injury Comparison:** GMT800 SDM Switch Contact Bounce.

**Potential Field Remedy:** Add key "inserts" - \$14.2M. Replace ignition switch - \$37.7M.

**Potential Field Action Category:** Safety Recall

## Chronology:

- 10/29/04 PRTS N182276 issued. For ignition key low effort, may turn while driving. Closed w/o action (Code 19 – part met requirements).
- 6/23/05 Investigation opened on 2005 Cobalt stall – Focus on key rotation.
- 6/28/05 Investigation closed: Plan for Bulletin adding insert and possibly changing key from slot to hole.
- 11/28/05 Service Bulletin #05-2-35-007 issued to remedy inadvertent turning of key cylinder (reduce content on key chain and add insert).
- 4/26/06 Ignition switch PPAP completed with new plunger and spring (effort increase). No P/N change, production implementation date unknown.
- 8/1/09 Ignition key changed from slot to hole.
- 7/1/11 Service Bulletin #05-2-35-007 updated to add model years.
- 8/24/11 Investigator assigned for airbag nondeployment.

From Aug 2011 to Dec 2013

- Management updates
- Red X Study
- DFSS Project
- Outside consultant analysis


Backup



Cobalt

Not applicable

# TORQUE vs. ROTATION




20 +/- 5 N-cm

- ACC - RUN
- RUN - ACC

IGNITION SYSTEM TORQUE REQUIREMENTS

## Torque to Rotate From Run to Accessory



**The Chevrolet Cobalt began production with the Saturn Ion ignition switch.  
All model years Cobalt, Pursuit, G5, Ion and HHR use same ignition switch part number.**

### **Ignition Switch Position from SDM Download - Incident Vehicles**

2005-2007 Cobalt, Pursuit (Canada only) & 2007 G5<sup>A</sup>

13 Accessory

1 Off

8 Run

1 No Event (not recorded)

2008 – 2010 Cobalt, Pursuit, G5

0

2003-2006 Ion

2 Not available from SDM<sup>B</sup>

2006-2008 HHR

0

### **Cobalt versus Ion (2 Potential Incidents) & HHR (No Reports)**


- Review indicates 2 potential non-deploys for Ion, but are not confirmed to be the same cause.
- Ion has different column shroud which could affect potential for key interaction
- HHR has more clearance to the driver's knee

<sup>A</sup> One G5 incident, all others are Cobalt.

<sup>B</sup> Ion uses Class 2 architecture which does not record in ACCESSORY. Cobalt, G5 & HHR use the GM LAN which records to the SDM even with ignition in ACCESSORY




# Torque to Rotate From Run to Accessory






## Non-Deployment Allegations by Model Year Cobalt (22), G5 (1)



- The mechanical characteristics of the ignition switch were unchanged for all model years.
- A revision to the switch occurred during the 2007 MY to increase the torque to rotate.
  - The part number was not changed and the breakpoint is unknown.
  - Incidents within the 2007 MY are distributed throughout the build months.


# 2005-7 Cobalt/G5 Non Deploy Incidents & Population by MOB



Build date not available for one 2005 vehicle

As of 10/1/13

# 2005-7 Cobalt / G5 Reports of Airbag Non-Deploy by Model Year & Incident Date




As of 10/1/13

| Stalling VOQs by Model Year                                   |      |      |      |      |      |      |      |      |
|---|------|------|------|------|------|------|------|------|
| Potential Key Motion (Stall with No DTCs & Immediate Restart) |      |      |      |      |      |      |      |      |
| Model   | 2003 | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 |
| COBALT  |      |      | 12   | 13   | 1    | 1    | 1    |      |
| HHR   |      |      |      | 11   | 2    | 1    |      |      |
| ION   | 1    | 2    |      | 8    |      |      |      |      |


| 2005-10 Cobalt TREAD Search - Elec, Eng, Strg Potential Knee-Key |      |      |      |      |      |       |
|--|------|------|------|------|------|-------|
| 2005   | 2006 | 2007 | 2008 | 2009 | 2010 | Total |
| 56   | 43   | 10   | 1    | 0    | 0    | 110   |




# 2005-2009 Cobalt VOQs for Potential Ignition off While Driving



# 2003-9 Ion, HHR VOQs for Potential Ignition off While Driving



# 2003-9 Ion, Cobalt, HHR, VOQs for Potential Ignition off While Driving







**#05-02-35-007 Information on Inadvertent Turning of Key Cylinder, Loss of Electrical System and No DTCs -**

- Issued Nov 2005
- Reissued July 2011 to add the 2007 MY.

Subject: Information on Inadvertent Turning of Key Cylinder, Loss of Electrical System and No DTCs




**This bulletin is being revised to add a model year. Please discard Corporate Bulletin Number 05-02-35-007 (Section 02 – Steering).**

There is potential for the driver to inadvertently turn off the ignition due to low ignition key cylinder torque/effort.


The concern is more likely to occur if the driver is short and has a large and/or heavy key chain. In these cases, this condition was documented and the driver's knee would contact the key chain while the vehicle was turning and the steering column was adjusted all the way down. This is more likely to happen to a person who is short, as they will have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and should take steps to prevent it – such as removing unessential items from their key chain.

Engineering has come up with an insert for the key ring so that it goes from a "slot" design to a hole design. As a result, the key ring cannot move up and down in the slot any longer – it can only rotate on the hole. In addition, the previous key ring has been replaced with a smaller, 13 mm (0.5 in) design. This will result in the keys not hanging as low as in the past.



## Key Insert Claims by Build Month P/N 15842334




| MODEL        | 2005       | 2006       | 2007      | Total      |
|--------------|------------|------------|-----------|------------|
| Cobalt       | 169        | 71         | 6         | 246        |
| G5           |            |            | 4         | 4          |
| HHR          |            | 35         | 2         | 37         |
| ION          | 51         | 98         | 33        | 182        |
| Pursuit      | 12         | 9          |           | 21         |
| Solstice     |            | 4          | 1         | 5          |
| <b>Total</b> | <b>232</b> | <b>217</b> | <b>46</b> | <b>495</b> |

Key  
Slot vs. Hole  
Cobalt



2005 Salvage Yard Cobalt

2008 Salvage Yard Cobalt




- Ignition switch with increased effort passed validation 4/26/06.
- Part number not changed.
- Implementation date is unknown.


- 12 spring coils
- Run to Acc: -7.7 N-cm
- Cap is shorter than observed in MY 07+ and aftermarket switches

- 15 spring coils
- Run to Acc: -22.6 N-cm


# Torque to Rotate From Run to Accessory



# Torque to Rotate From Run to Accessory



# 2005-7 Cobalt/G5 Non Deploy Incidents & Population by MOB



Build date not available for one 2005 vehicle

As of 10/1/13



# Torque Gauge Measurements (Steering Columns from Salvage Yards)

| Model Year | Model & VIN        | P/N      | Cap Size | Off to Acc (N-cm) | Acc to Run (N-cm) | Run to Start (N-cm) | Run to Acc (N-cm) | Acc to Off (N-cm) |
|------------|--------------------|----------|----------|-------------------|-------------------|---------------------|-------------------|-------------------|
| 2005       | Cobalt<br>VIN 1306 | 10392423 | Short    | 2.8               | 7.4               | 50.9                | -6.0              | -6.7              |
| 2005       | Cobalt<br>VIN 2380 | 10392423 | Short    | 3.2               | 7.8               | 48.0                | -7.8              | -8.1              |
| 2006       | Cobalt<br>VIN 7326 | 10392423 | Short    | 2.1               | 7.8               | 50.9                | -7.1              | -8.1              |
| 2006       | Cobalt<br>VIN 6342 | 10392423 | Short    | 2.1               | 8.5               | 50.9                | -7.8              | -8.5              |
| 2007       | Cobalt<br>VIN 9561 | 10392423 | Long     | 3.5               | 19.8              | 50.9                | -16.2             | -16.2             |
| 2008       | Cobalt<br>VIN 4195 | 15886190 | Long     | 5.3               | 19.8              | 48.0                | -22.6             | -22.6             |
| 2008       | Cobalt<br>VIN 0386 | 15886190 | Long     | 4.9               | 17.0              | 48.0                | -19.8             | -22.6             |
| 2009       | Cobalt<br>VIN 3438 | 15886190 | Long     | 3.2               | 19.8              | 53.7                | -15.5             | -15.9             |

DRAFT Privileged and Confidential  
Attorney Work Product



**Non-deploys due to Ignition Switch Rotation**

2005-7 Cobalt, G5, Pursuit, 2003-2007 Ion, 2006-2007 HHR

|                         | Incident Reports     | U.S. Population | IPHTV / Year Exposure |
|-------------------------|----------------------|-----------------|-----------------------|
| <b>2005-2007 Cobalt</b> | <b>23</b>            | <b>618,014</b>  | <b>0.47</b>           |
| 2005 Cobalt             | 11                   | 140,646         | 0.89                  |
| 2006 Cobalt             | 7                    | 229,231         | 0.38                  |
| 2007 Cobalt             | 5                    | 248,137         | 0.29                  |
| <b>2006-2007 HHR</b>    | <b>0</b>             | <b>214,072</b>  | <b>0</b>              |
| <b>2003-2007 Ion</b>    | <b>2<sup>A</sup></b> | <b>478,986</b>  | <b>0.04</b>           |


<sup>A</sup> Incidents can not be confirmed to be due to ignition switch rotation.

**SDM Sensor Bounce Anomaly – Safety Recall - Decision June 2002 (approx.. 2 yrs. Exposure)**


2000 GMT800 (Safety); 2000 S/T (No field action); 2000 M/L (No field action)

|                    | Incident Reports | Population     | IPHTV / Year Exposure |
|--------------------|------------------|----------------|-----------------------|
| <b>2000 GMT800</b> | <b>9</b>         | <b>572,108</b> | <b>0.70</b>           |
| <b>2000 S/T</b>    | <b>1</b>         | <b>455,500</b> | <b>0.11</b>           |
| <b>2000 M/L</b>    | <b>0</b>         | <b>96,328</b>  | <b>0</b>              |

# Cobalt – Front Airbag Non-Deployment Incidents Per 100K Vehicles



# Severity of Injuries: 2005-7 Cobalt / G5 Reports of Airbag Non-Deploy



## Severity Summary:

- 7 mild
- 9 moderate
- 2 severe
- 5 fatal

As of 10/1/13

## Injury Severity Comparison

### 2000 GMT800 Sensor Bounce: 9 Total (3 mild, 3 moderate, 2 severe, 1 fatal)

|   |          |
|---|----------|
| Fatal   | fatal    |
| Skull & nose fracture, laceration right side of face & mouth. Whiplash. Lost consciousness. Wrist, knee, ankle, and foot injury. 6 days ICU | Severe   |
| Belted - Significant head and chest & lower leg injury.   | Severe   |
| Fractured neck vertebrae  | moderate |
| Fractured neck vertebrae. Fractured shoulder  | moderate |
| Concussion, sore shoulder, and chest  | moderate |
| No treatment. Claimed chest injury  | mild     |
| Head trauma, bruises - treated at hospital  | mild     |
| Broken nose   | mild     |

### 2005-2007 Cobalt, G5, Pursuit: 23 Total (7 mild, 9 moderate, 2 severe, 5 fatal)

|   |           |
|---|-----------|
| Fatality  | Fatal     |
| Fatality  | Fatal     |
| Driver & Front Passenger: Fatal   | Fatal (2) |
| Fatality  | Fatal     |
| Fatality  | Fatal     |
| Traumatic Brain Injury  | Severe    |
| Quadriplegic  | Severe    |
| Bruising to left side of head, cuts to left knee and back P: Fractured ribs, shoulder blade, cuts, and bruises      | Moderate  |
| Unknown Injuries (D) P: Broken neck (w/o paralysis), fractured ribs, sternum, laceration to head, facial bruises    | Moderate  |
| Fractured ribs, nose, femur, and ankle  | Moderate  |
| Fractured vertebrae and severe ear laceration   | Moderate  |
| Kidney damage, left arm fracture, internal bleeding   | Moderate  |
| Lost teeth, several stiches in mouth, broken ankle, broken wrist  | Moderate  |
| Syncope, concussion, occipital laceration, multiple contusions, seizure disorder                                    | Moderate  |
| Fractured nose & scapula P:fractured leg  | Moderate  |
| Severe TBI, Basilar skull fracture, right hip fracture, right sacral fracture                                       | Moderate  |
| Facial FX including: R. Orbital floor, R. Maxillary Sinus, and Bilateral Nasal Bone. Facial laceration & concussion | Mild      |
| Bruised chest area, Bruises on head   | Mild      |
| Fractured front teeth and multiple contusions   | Mild      |
| Laceration to liver, cut nose, bruised chest, bumps all over, sore left knee  | Mild      |
| Laceration to head with scarring  | Mild      |
| Facial Laceration and dislocated hip  | Mild      |
| Broken nose , broken cheekbone, bruised lung, pain in right elbow   | Mild      |

***Non-deploys due to Ignition Switch Rotation***

***2005-7 Cobalt, G5, Pursuit, 2003-2007 Ion, 2006-2007 HHR***

|                         | <b>Incidents Per 100k Vehicles /Year Exposure</b> |                  |                  |
|-------------------------|---|------------------|------------------|
|                         | <b>Cumulative</b>                                 | <b>2005-2008</b> | <b>2009-2013</b> |
| <b>2005-2007 Cobalt</b> | <b>0.47</b>                                       | <b>0.86</b>      | <b>0.20</b>      |
| 2005 Cobalt             | 0.89  | 1.42             | 0.45             |
| 2006 Cobalt             | 0.38  | 0.58             | 0.28             |
| 2007 Cobalt             | 0.29  | 0.81             | 0.09             |

***SDM Sensor Bounce Anomaly – Decision June 2002 (approx. 2 yrs. Exposure)***

*2000 GMT800 - Safety Recall*


*2000 S/T - No field action.*

|                    | <b>Incident Reports</b> | <b>Population</b> | <b>IPTV / Year Exposure</b> |
|--------------------|-------------------------|-------------------|-----------------------------|
| <b>2000 GMT800</b> | <b>9</b>                | <b>572,108</b>    | <b>0.70</b>                 |
| <b>2000 S/T</b>    | <b>1</b>                | <b>455,500</b>    | <b>0.11</b>                 |
| <b>2000 M/L</b>    | <b>0</b>                | <b>96,328</b>     | <b>0</b>                    |

# Cost Estimates (Includes Vehicle Attrition)

## GM Accrual Cost Estimate

|  | Ignition Switch | 2 Ignition Keys | 2 Key Inserts |
|--|-----------------|-----------------|---------------|
| 2005-6 Cobalt                              | \$22,149,270    | \$21,341,858    | \$8,383,201   |
| 2005-7 Cobalt, G5*                         | \$37,722,764    | \$36,347,646    | \$14,277,558  |
| 2005-7 Cobalt, G5*, 2003-7 Ion             | \$69,772,734    | \$60,877,738    | \$23,913,115  |
| 2005-7 Cobalt, G5*, 2003-7 Ion, 2006-7 HHR | \$81,150,684    | \$71,840,926    | \$28,219,516  |



**Replace Switch**



**Exchange:  
2 slotted w/  
2 holes**



**Add Insert**

| Production Year      | 2003          | 2004           | 2005           | 2006           | 2007           | Total            |
|----------------------|---------------|----------------|----------------|----------------|----------------|------------------|
| Cobalt, G5, Pursuit* | N/A           | N/A            | 154,807        | 261,924        | 293,010        | 709,741          |
| Ion                  | 88,926        | 113,028        | 74,677         | 100,436        | 101,919        | 478,986          |
| HHR                  | N/A           | N/A            | N/A            | 113,003        | 101,069        | 214,072          |
| <b>Total</b>         | <b>88,926</b> | <b>113,028</b> | <b>229,483</b> | <b>475,364</b> | <b>495,998</b> | <b>1,402,799</b> |

# Summary Points

A) Combined reports (FPA, VOQs, Tread) indicate that a distinct change occurred during 2007 MY:

| 2005 MY | 2006 MY | 2007 MY | 2008 MY | 2009 MY | 2010 MY |
|---------|---------|---------|---------|---------|---------|
| 79      | 63      | 16      | 2       | 1       | 0       |

B) The non-deployment incident rate for 2005 MY is over 2 times higher than 2006; approx. 3 times higher than 2007 MY.

|                    | <u>2005</u> | <u>2006</u> | <u>2007</u> |
|--------------------|-------------|-------------|-------------|
| Incidents          | 11          | 7           | 5           |
| IPHTV/Yrs Exposure | 0.89        | 0.39        | 0.30        |

(Combined IPTV/Yrs Exposure = 0.47 IPHTV)

C) 2005 MY incident rate is higher than the GMT800 (SDM Contact Bounce) field action which was at 0.77 IPHTV at the time of decision.

D) All Model Years show a decreasing trend. Reported non-deployment incidents within the last 5 years are significantly lower compared to the first 4 years of exposure.

|                    | <u>2005</u> | <u>2006</u> | <u>2007</u> |
|--------------------|-------------|-------------|-------------|
| 2005-2008          | 8           | 4           | 4           |
| IPHTV/Yrs Exposure | 1.42        | 0.58        | 0.81        |
| 2009-2013          | 3           | 3           | 1           |
| IPHTV/Yrs Exposure | 0.45        | 0.28        | 0.09        |

There have been 2 reports in the past 34 months.

E) The change to the ignition switch that was introduced during the 2007 Model Year (possibly Oct '06) is directionally correct. Four incidents have occurred on vehicles built after this date.

F) Changing the key from a slot to a hole is directionally correct.



---

**From:** Brian Stouffer

**Sent:** Monday, December 02, 2013 8:14 PM

**To:** [Grejb](#), Gary R

**Cc:** John Murawa; Mark A Johnson

**Subject:** Request for PPAP & Quality Plan Data for Chevrolet Cobalt Ignition Switch P/N 10392423

The information you provided on the change to the Cobalt ignition switch plunger and spring has been very helpful.

Today, I gave an update to some of our directors regarding the status of the investigation into 2005-7 Cobalt frontal airbag non-deployments. I was asked to get the actual PPAP data and not just warrants for the switch in 2005 and then when the plunger and spring change was approved in April 2006 (Change Approval Longer Spring & Plunger 57128dat.doc). Specifically, the data for the switch torque testing is requested (see Ignition Switch Torque Requirements.pptx) attached.

In addition to the torque data for PPAP, any KPC data that was taken from the 2005 – 2008 model years is desired. Torque curves are the item of primary interest. Ultimately, any data taken to support the quality plan is desired.

I understand it may take a several days to gather the requested information. That is significant because my last day of work at GM is Wednesday December 4, 2013. I will be on vacation from that point on until my official retirement 2/1/14 (30 years). Another member of my group will be taking over this project. He is John Murawa. I've included him on this e-mail. His contact information is:



**From:** Greib, Gary R [REDACTED]

**Sent:** Tuesday, December 10, 2013 7:10 AM

**To:** John Murawa

**Subject:** FW: Request for Information Chevrolet Cobalt Ignition Switch P/N 10392423

John – See below and attached. There appears to be some torque testing data in the attached PPAP sign-off. If there are more specifics, please spell-out exactly what you are looking for and I will forward it on to the plant.

Gary R. Greib

Manager, Product Investigations / Patent Agent

Delphi Legal Staff

**From:** Cuervo, Antero

**Sent:** Monday, December 09, 2013 5:46 PM

**To:** Greib, Gary R

**Cc:** Lopez Martinez, Guadalupe; Miller, Lyle D; Villarreal, Mauricio

**Subject:** FW: Request for Information Chevrolet Cobalt Ignition Switch P/N 10392423

Gary, our PPAP coordinator found the following documentation. It is a newer warrant with some validation data attached. No data related to the original warrant was found.

# GENERAL MOTORS COMMODITY VALIDATION SIGN-OFF \*\*

Pg. 1 of 2

Buyer's concurrence on the Seller's completion of validation shall not limit, impair, or otherwise modify Buyer's right to assert any legal or equitable remedy, or relieve Seller of its responsibility to provide conforming goods.

March 17, 2006

|  |   |   |                              |
|--|---|---|------------------------------|
| Part Name* <b>GMX001/002 IGNITION SW</b>   |   | Part Number* <b>15986190</b>                    |                              |
|  |   | Rev <b>001</b>                                  |                              |
| Shown on Drawing No.* <b>15986190</b>      |   | Eng'g Design Record <b>001</b>                  | Dated* <b>March 17, 2006</b> |
|  |   | Change Level*                                   |                              |
| Procuring Division* <b>NAC</b>             | Application Program* <b>G480021/002</b> | Purchase Order No.* <b>1336 (JTEK)</b>          |                              |
| GM Lead Engineer* <b>Raymond DeGiorgio</b> |   | GM Validation Engineer* <b>Eugene P Carnage</b> |                              |
| Supplier Resident Engineer <b>N/A</b>      |   |   |                              |

### SUPPLIER MANUFACTURING INFORMATION

Supplier Name\* **Delphi Mechatronic Systems** DUNS Number\* **812502961**  
 Street Address\* [REDACTED]

### REASON FOR SUBMISSION\*

Initial Submission     Re-submission due to Engineering Changes     Re-submission to correct problems in initial submission  
 EWO #(s) **WO 572658**

### COMMODITY VALIDATION SIGN-OFF REQUIREMENTS

Specified by Procuring Division in Appendix G2 (or G) and GMN0900 or in separate written request.  
 Page 2 lists more information about the required documentation.

|  | YES                                 | NO                       | Not Req'd by SOR                    |
|--|-------------------------------------|--------------------------|-------------------------------------|
| 1. Supplier has submitted the required 'Proof of Validation Letter' as specified in GMN0900 Section 5.1 and any required regulatory compliance documentation.  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| 2. The Supplier has completed execution of their ADV Plan(s) including activities to resolve issues identified during development and validation.  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| 3. All ADV issues that are the responsibility of the Supplier have been addressed and classified as 'closed'. This includes those Supplier commodity issues identified during development, design validation, or product validation, validation assurance testing and post-validation audits whether or not those issues are tracked by GM or by the Supplier. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| 4. The information in the Supplier's issue tracking system has been updated and is consistent with the final resolution of all ADV issues.   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| 5. The Supplier has completed its final ADV PSR (GM1828) which indicates completion of validation to the technical requirements as specified in the Final Technical Specification, approved Engineering Work Order or in writing by GM.  | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| 6. All other ADV tasks/deliverables specified in the SOR are complete.   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |                                     |
| 7. If applicable, all regulatory compliance evaluation reports and documentation have been completed and documents requested by GM have been submitted to the Validation Engineer.   | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 8. If applicable, the Supplier shall have obtained approval of the detailed validation results for those product technical requirements for which GM approval was specified in the 'Other Validation Requirements' column of the Final VGR1 in SOR Appendix G2 (or G) or an approved Engineering Work Order.   | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 9. The Supplier has submitted to the GM CAE Engineer for the commodity the models required for the Virtual Archive Vehicle as specified in the SOR.  | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 10. Other: <u>Validation for carry over program GMX001 with Resistor value of 1.3 kOhms.</u>   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

Controlling the amount of grease in the PCB assembly

Explanation of 'NO' answers or comments here:  
 \_\_\_\_\_  
 \_\_\_\_\_

Supplier Name (please print)\* **Merary Gonzalez** Title\* **Product En** Phone No\* [REDACTED]  
 Supplier Authorized Signature\* [REDACTED] Dated\* **05/02/07**

**GM DECISION:** Rejected  (see comments)    Re-submit  (see comments)    Only Req'ds 1 & 5 met  (see comments)    Sign-Off  Complete

GM Validation Engineer Name (please print) **Eugene Carnage** Phone\* [REDACTED]  
 GM Validation Engineer Signature\* [REDACTED] Date\* **3.21.07**  
 GM Lead Engineer Name\* (please print) **Raymond DeGiorgio** Phone\* [REDACTED]  
 GM Lead Engineer Signature\* [REDACTED] Code: **G204** Date\* **5/3/07**

Comments:

**Analysis/Development/Validation Plan & Report (ADV P & R) — GM 1829**

|  |   |   |   |
|--|---|---|---|
| <b>SECTION I — COMMODITY DESCRIPTION</b>   |   | <b>SECTION II A — SUPPLIER INFORMATION</b>  |   |
| PART # 145742 (1000)<br>PART NAME 455 (HEAT SHIELD BRACKET)<br>QTY #<br>REVISION LEVEL RELEASE DATES | MODEL YEAR 2005<br>PLANT CODE SM04190<br>MODEL # CH | SUPPLIER CODE<br>SUPPLIER CONTACT<br>SUPPLIER CONTACT PHONE NUMBER<br>SUPPLIER CONTACT'S MAIL ADDRESS | DUNS NUMBER<br>SOURCE QUALITY PROGRAM<br>[REDACTED]<br>[REDACTED] |

|   |   |                               |
|---|---|-------------------------------|
| <b>SECTION II B — GM CONTACT INFORMATION/APPROVAL</b> |   | <b>DATE:</b> 2/24/07          |
| GM VALIDATION ENGINEER NAME<br>PHONE NUMBER AND EXT.  | GM ORGANIZATION DIVISION<br>3.1.1.0<br>PHONE NUMBER | GM IN CHARGE<br>NAME AND EXT. |

| <b>SECTION III — ADV PLAN SUMMARY</b> |             |                                   |         |  |            |  |                 |            |        |        |      |       |      |                |      |       |  |                                   |
|---------------------------------------|-------------|-----------------------------------|---------|--|------------|--|-----------------|------------|--------|--------|------|-------|------|----------------|------|-------|--|-----------------------------------|
| ITEM #                                | PROCEDURE # | PROCEDURE TITLE                   | REQMT # | REQMT TITLE                            | REGULATORY | REQMT VALUE  | RESPON SIBILITY | EVALUATION |        | SAMPLE |      | TRNG  |      | SAMPLES TESTED |      |       | RESULTS  | NOTES                             |
|                                       |             |                                   |         |  |            |  |                 | PHASE      | METHOD | QTY    | TYPE | START | COMP | QTY            | TYPE | STAGE |  |                                   |
| 1                                     | 1240220     | COMPONENT TECHNICAL SPECIFICATION | 3.2.1.3 | Voltage Drop                           | USA        | 350 mV Max.  | DELPHI          | PWA        | Y      | 12     | F    | 4567  | 4567 | 12             | F    | Prod. | Met Requirements   |                                   |
| 2                                     | 1240220     | COMPONENT TECHNICAL SPECIFICATION | 3.2.1.5 | Open Circuit Resistance                | USA        | 30 Mohm Min.   | DELPHI          | PWA        | Y      | 12     | F    | 4567  | 4567 | 12             | F    | Prod. | Met Requirements   |                                   |
| 3                                     | 1240220     | COMPONENT TECHNICAL SPECIFICATION | 3.2.1.8 | Insulation Resistance                  | USA        | 30 Mohm Min.   | DELPHI          | PWA        | Y      | 12     | F    | 4567  | 4567 | 12             | F    | Prod. | Met Requirements   |                                   |
| 4                                     | 1240220     | COMPONENT TECHNICAL SPECIFICATION | 3.2.2.3 | Tensile Characteristics (Torque-Angle) | USA        | Adhesion Torque AS in draw<br>Stick-shear (As per Drawing) | DELPHI          | PWA        | Y      | 12     | F    | 4567  | 4567 | 12             | F    | Prod. | Did not meet requirements<br>[Handwritten notes and signature] | [Handwritten notes and signature] |

*Evaluation Applied  
TABLE CHARACTERISTICS  
E 3 mat*

# 2005-7 Cobalt, G5, Pursuit, 2003-2007 Ion, 2006-2007 HHR

## Condition:

A review of selected Cobalt & G5 frontal crash events indicates some airbag non deploys have occurred where the ignition switch was in accessory or off. The condition appears to be limited to 2005-07 Cobalt & G5 vehicles. The noted field events involve vehicles going off the road and/or hitting smaller objects shortly before a more significant impact.

## Questions:

- Why no incidents on Ion or HHR
  - Ion is Class 2 architecture vs GM LAN on Cobalt and HHR
    - Both disable SDM with key off, but Cobalt/HHR will store ignition state & crash record while Ion will not
    - NISM review indicates 2 potential non-deploys for Ion
  - Ion has different column shroud which could affect potential for key interaction
  - Ion customers may be less likely to have the type of crash needed for the condition
  - Ion has different SDM and supplier than Cobalt
  - HHR has more clearance to the driver's knee
- Why no incidents on 2008-10 Cobalt?
  - Ignition switch was revised to have longer plunger and spring to increase effort (confirmed 10/29/13)
    - Part number not changed, so implementation date is unknown (Validation complete 4/26/06). Salvage yard samples included 2007 vehicles with longer plunger (unknown if any had been replaced in service).

## Root Cause:

- The hypothesis is that during the off road event the driver's knee is interacting with the keys and/or the mass of the keys is causing the ignition to rotate

# Vehicle Population & Incident Rate 2005-2007

## Vehicles Sold in US

|                    | <u>2005</u>   | <u>2006</u>   | <u>2007</u>    |
|--------------------|---------------|---------------|----------------|
| Cobalt/G5# Pursuit | 140,464       | 229,231       | 248,137        |
| Incidents          | 11            | 7             | 5              |
| IPTV/Yrs Exposure  | 0.0089        | 0.0039        | 0.0030         |
| SOP – 1/1/09       | 8             | 4             | 4              |
| IPTV/Yrs Exposure  | 0.0142        | 0.0058        | 0.0081         |
| 1/1/09-10/1/13     | 3             | 3             | 1              |
| IPTV/Yrs Exposure  | <b>0.0045</b> | <b>0.0028</b> | <b>0.00085</b> |

- 2000 GMT800 0.0070 IPTV/yr (approx 2 yrs exposure @ decision June 2002)
- 2000 S/T truck 0.0011 IPTV/yr no field action
  - SDM anomaly may result in no-deploy

# Vehicle Population & Incident Rate 2005-2007

## Cobalt & G5

### Vehicles Sold in US

|                    | <u>2005</u> | <u>2006</u> | <u>2007#</u> |
|--------------------|-------------|-------------|--------------|
| Cobalt/G5# Pursuit | 140,464     | 229,231     | 248,137      |

|                   |        |        |        |
|-------------------|--------|--------|--------|
| Incidents*        | 11     | 7      | 5      |
| IPTV/Yrs Exposure | 0.0089 | 0.0039 | 0.0030 |

(as of 10/1/13)

Incident rate for 2005 is over 2 times higher than 2006 and about 3 times higher than 2007

Combined IPTV/Yrs Exposure 0.0053

\*Except for 1 2007 G5, all reports are Cobalt. There is 1 incident reported on a 2008 vehicle. 2008 vehicle had front sensor fault that disabled system prior to crash.

# G5 was 2007 start.

# Test Set-up Using Torque Tool



Measure torque (Ncm)  
to rotate key from Run  
To Accessory

# TREAD Search July 2012 (TAC & CAC)

## Stalling with No DTCs

| IPTV/yr    | 2003    | 2004    | 2005    | 2006    | 2007    | 2008 | 2009 |
|------------|---------|---------|---------|---------|---------|------|------|
| Cobalt, G5 | N/A     | N/A     | 0.05316 | 0.02886 | 0.00733 | ~0   | 0    |
| Ion        | 0.04046 | 0.02526 | 0.04346 | 0.01826 | 0.0     | N/A  | N/A  |



# Cobalt, Ion & HHR Ignition Switch Measurement

- 5/22/12 44 vehicles in Davison salvage yard
  - Measured torque (Ncm) and force (N) to turn the ignition switch from Run to Accessory.
    - Five of the vehicles had a replacement key, or a key with a hole vs slot (force not measured)

|             | Model Year |      |      |      |      |      |      |      |             |
|-------------|------------|------|------|------|------|------|------|------|-------------|
| Model       | 2003       | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | Grand Total |
| Cobalt      |            |      | 1    | 5    | 5    | 3    | 3    | 1    | 18          |
| G5          |            |      |      |      | 1    |      | 1    |      | 2           |
| HHR         |            |      |      | 4    | 3    | 2    | 1    | 1    | 11          |
| Ion         | 2          | 5    | 3    | 1    | 2    |      |      |      | 13          |
| Grand Total | 2          | 5    | 4    | 10   | 11   | 5    | 5    | 2    | 44          |

# Switch Background

- Ion switch original for 2003. For 2005 capacity tooling was needed for Cobalt. The part number is the same, so it is not known what cavities were used for Ion and then for Cobalt. HHR added in 2006
  - A change was initiated in 2006 to implement a new printed circuit board (12861211 Rev 5) and a new detent plunger (741-79378). The taller plunger and spring with more coils completed validation testing 4/24/06. The switch p/n was not changed, so it is unknown when switches with the new content were put into production or service.\*

*\*The change to the plunger and spring was not confirmed until Delphi provided details with that information on 10/29/13*


# 2003 Ion vs 2007 Cobalt



# HHR Knee Clearance to Ignition (6'1" driver)



# 2005-7 Cobalt / G5 Reports of Airbag Non-Deploy by Model Year & Incident Date




R\* = Run but algorithm disabled


As of 10/1/13

# Ignition Cylinder Warranty (N100256)


**CTS**  
(Sidebar w/Retainer)




**HHR**  
(Sidebar w/Retainer)



**Cobalt**  
(Sidebar w/Retainer)




**07 Saturn ION**  
(Sidebar w/Retainer)



# Assessment SDM Change

- Changing the SDM power down behavior is high risk. The power moding, fail safe operation, and diagnostics portion of the SW would need to be modified.
  - The start up behavior, i.e. driver seat belt reminder would still need to be compliant – even though there was no change to the “internal power mode” of the SDM on a quick IGN cycle.
  - Diagnostics of the IGN line and AOS module (perhaps other U-Codes) would need to be modified
  - Changes to the design of the SDM will need to be done by engineers who were not part of the original design team.
- Note that the AOS module is powered from IGN not battery – so it will power off when the key transitions from run. The FMVSS requirement is that the correct airbag state be displayed within 10 secs – so if the SDM shut off delay lasted longer than 10 seconds or if a transition of airbag state happened with 2-3 seconds of power mode change, there may be a violation of this requirement.



# Vehicle Scrap Rates

| <u>AGE</u> | <u>TRUCKS</u><br><u>(Full Size</u><br><u>Trucks</u><br><u>and Vans)</u> | <u>CARS</u><br><u>(All</u><br><u>others)</u> |
|------------|---|--|
| 1          | 100%  | 100%   |
| 2          | 99%   | 99%  |
| 3          | 99%   | 99%  |
| 4          | 98%   | 97%  |
| 5          | 95%   | 95%  |
| 6          | 94%   | 93%  |
| 7          | 93%   | 92%  |
| 8          | 92%   | 91%  |
| 9          | 92%   | 89%  |
| 10         | 91%   | 85%  |
| 11         | 86%   | 82%  |
| 12         | 79%   | 76%  |

*\*data pulled by RL Polk in March 2012*



# 2003 Ion vs 2007 Cobalt

