



2005-2007 Cobalt/Pursuit/G5

ETQ N-130454

Ignition Switch

778,563 Vehicles

Cost Estimate: \$41.3M

Locations: US, CAN, MEX

Condition:

Front airbag non-deployment has been identified in certain crash events. In those events the ignition switch had moved from RUN to ACCESSORY or OFF.

Effects: The airbags will not deploy if the ignition has moved from RUN.

Root Cause: The ignition switch torque performance may be below specifications.

Service Bulletin: Bulletin #05-2-35-007 – Inadvertent key turning – issued Oct 2005.

Number of Reports:

- 23 allegations of front airbag nondeployment.
Field incidents involve vehicles going off the road or hitting smaller objects shortly before a more significant impact.
- 26 VOQs for “Ignition Off” while driving.
- 355 TREAD reports or application of Service Bulletin.

Ignition Switch Change: Increased effort for RUN to ACCESSORY.

Rate & Injury Comparison: GMT800 SDM Switch Contact Bounce.

Potential Field Remedy: Add key inserts on all, replace ignition switch builds < Nov ‘06.

Potential Field Action Category: Safety Recall


Follow-up from December 17, 2013 FADC Review:

1. Forces required to rotate ignition from RUN to ACCESSORY/OFF
 - Mass/number of keys
 - Road inputs (rough road data – interior accelerations)

2. Knee Clearance to Key Cylinder
 - GM Fleet vs. Cobalt


3. Power Mode Deactivation Delay
 - Extend the time the SDM algorithm remains active after the vehicle exits the RUN power mode.

Salvage Yard Vehicle Measurements Torque to Rotate From Run Position



Salvage Yard Vehicle Measurements

Torque to Rotate From Run Position



Original Switches only.

1. Forces required to rotate ignition from RUN to ACCESSORY/OFF



Static Key Ring Mass (lbs.) to Rotate Ignition Switch from Run

Switch Force	Column Position		
	Low	Mid	High
25 N-cm	5.20	4.97	4.49
20 N-cm	4.16	3.97	3.59
15 N-cm	3.12	2.98	2.70
10 N-cm	2.08	1.99	1.80


Switch Specification = 20 +/- 5 N-cm

Internal Cylinder Force (approx.) = 2 N-cm

Column High to Low

Salvage Yard Vehicle Measurements

Static System Torque to Rotate From Run




Spec. = 20
+/- 5 N-cm

Original Switches only.

Column High to Low

Salvage Yard Vehicle Measurements

Static System Torque to Rotate From Run



Torque (Ncm)




	Measured Weights	
Standard Fob	20 g	0.0441 lbs.
Overmold Key	15 g	0.0331 lbs.
Std Lockset Key	12 g	0.0264 lbs.
Gen I Flip Key	45 g	0.0992 lbs.
Total	92 g	0.2028 lbs.

Original Switches only.

Cadillac ATS Rough Road Testing – Interior Accelerations @ SDM / MPG Evaluations


Test	Speed	Z Accel. Max
550/629 Hop	30 MPH	7.25 G
550/629 Tramp	30 MPH	4.87 G
Square Block	30 MPH	5.42 G
Washboard	40 MPH	5.06 G
#3 Pothole	25 MPH	13.10 G
Chatter Bumps	60 MPH	1.32 G
Massoit Bump	45 MPH	1.87 G
Curb Impact	5 MPH	1.88 G
Curb Drop-Off	20 MPH	2.83 G
Belgian Blocks	35/40 MPH	1.92 G



25mph Max Pothole #3

Column High to Low

Salvage Yard Vehicle Measurements Static System Torque to Rotate From Run




	Measured Weights		@ 13.1 G		
Standard Fob	20 g	0.0441 lbs.	0.58 lbs.	1.01 lbs.	2.66 lbs.
Overmold Key	15 g	0.0331 lbs.			
Std Lockset Key	12 g	0.0264 lbs.			
Gen I Flip Key	45 g	0.0992 lbs.			

Knee Clearance to Key Cylinder:

Model	Program	Knee to Cyl (MM)
Lacrosse	GMX353	55.8
Malibu	GMX351	56.4
Cruze	D1SC	58.9
Verano	D1SB	58.9
Impala	GMX352	67.7
Traverse	GMT561	70.7
	M2xx	73.4
	GMX521	73.9
Camaro	D2LC	76.2
	D2SB	76.2
	Cobalt	GMX001
Regal	GMX350	91.7
Spark	M1xx	92.4
Equinox	GMT172	106.7
Sonic	G1xx	149.2
Volt	D1JCI	Keyless
CTS	A1LL	Keyless
NG	E2SC	Keyless
SRX	GMT166	Keyless

RAMSIS Assumptions:

- 95th US male.
- H-pt located within seat travel box, mid travel (up/down).
- Posture prediction algorithm used.
- Distance calculated from right inner leg to center of key Cylinder face.
- Driver right ball of foot placed on center of brake pedal pad surface at unapplied position.



Ignition Cylinder JDP Comparison

High mount executions show lowest pph – low mount highest.





Colorado/Canyon – low mount and awkward key insertion




Equinox - mid mount – increases shroud width



Tahoe - high mount – eliminates ability to have RH wiper stalk



Extend the time the SDM algorithm is active after the vehicle exits the RUN power mode:



SDM: Software for power moding, fail safe operation, and diagnostics would require modification.


- Must address driver seat belt reminder (MVSS) on a quick ignition cycle.
- Requires modification to the diagnostics of the IGN line and AOS module (and other U-Codes).
- Software design changes would be done by Conti engineers who were not part of the original design team (originally Siemens).
- AOS: The occupant sensor module is powered from IGN and will power off when the key transitions from run. MVSS requirements for airbag state display would be violated if a transition of airbag state occurred within 2-3 seconds of power mode change.
- Not designed to be programmable. Approximately 25% would require replacement.
- Replacing with a newer (2011 MY) unit requires replacement of all crash sensors and crash testing to develop calibrations.
- Possible introduction of other issues or non-conformances that would be typically discovered in a full IVER.

Chronology:

- 10/29/04 PRTS N182276 issued. For ignition key low effort, may turn while driving. Closed w/o action (Code 19 – part met requirements).
- 6/23/05 Investigation opened on 2005 Cobalt stall – Focus on key rotation.
- 6/28/05 Investigation closed: Plan for Bulletin adding insert and possibly changing key from slot to hole.
- 11/28/05 Service Bulletin #05-2-35-007 issued to remedy inadvertent turning of key cylinder (reduce content on key chain and add insert).
- 4/26/06 Ignition switch PPAP completed with new plunger and spring (effort increase). No P/N change, production implementation date unknown.
- 8/1/09 Ignition key changed from slot to hole.
- 7/1/11 Service Bulletin #05-2-35-007 updated to add model years.
- 8/24/11 Investigator assigned for airbag nondeployment.
- From Aug 2011 to Dec 2013
- Management updates
 - Red X Study (2)
 - DFSS Project
 - Outside consultant analysis
- 10/29/13 Delphi confirms spring and plunger change made to switch. Validation completed 4/26/06. No part number change. Implementation date unknown.
- 12/17/13 FADC review.
- 12/19/13 FPET review.
- TBD FADC review.

Backup

Summary Points




	2005	2006	2007	2008	2009	2010
Total	248	134	22	2	1	0

1. The rate of reported stall or non-deployment incidents has decreased significantly from '05 to '06 without any known changes.
2. The rate of reported stall or non-deployment incidents from '06 to '07 has decreased significantly. 80% of the '07 MY reports are after the switch change (believed to have occurred Nov '06).
3. The 2008 and later models do not have any non-deployment allegations. There are no known differences between '07 MY (produced after Nov '06) and these vehicles.
4. The same switch is used on Ion and HHR which have a total of 2 unconfirmed reports.
5. Two thirds (16) of the non-deployment allegations occurred in the 4 calendar years from 2005-2008. Only one third (7) have occurred in the 5 calendar years from 2009-2013.
6. There have been only two non-deployment events in the last 3 calendar years. Random off road crashes should be continuous, not decreasing (91% of the vehicles are still in use).
7. Of the 12 VOQs for 2005MY, all occurred prior to Dec 2007.
8. The 2006MY VOQs (13) are consistent with the most recent Aug 2013.



December 8, 2006

- Evaluation of rotational effort of key locking/parklock cable system prior to lock cylinder durability.
- 2008 Prototype GMT-900 steering column assemblies tested per DTP.5014.1.44.






Lower Column Shroud (Key Bump)




Cobalt



Traverse

Not applicable

TORQUE vs. ROTATION




20 +/- 5 N-cm

- ACC - RUN
- RUN - ACC

IGNITION SYSTEM TORQUE REQUIREMENTS

Torque to Rotate From Run to Accessory



**The Chevrolet Cobalt began production with the Saturn Ion ignition switch.
All model years Cobalt, Pursuit, G5, Ion and HHR have the same mechanical properties for the ignition switch.**

Ignition Switch Position from SDM Download - Airbag Non-Deployment Incidents

2005-2007 Cobalt, Pursuit (Canada only) & 2007 G5^A

13	Accessory
1	Off
8	Run
1	No Event (not recorded)

2008 – 2010 Cobalt, Pursuit, G5

0

2003-2006 Ion

2 Not available from SDM^B

2006-2008 HHR

0

Cobalt versus Ion (2 Potential Incidents) & HHR (No Reports)


- Review indicates 2 potential non-deploys for Ion, but are not confirmed to be the same cause.
- Ion has different column shroud which could affect potential for key interaction
- HHR has more clearance to the driver's knee

^A One G5 incident, all others are Cobalt.


^B Ion uses Class 2 architecture which does not record in ACCESSORY. Cobalt, G5 & HHR use the GM LAN which records to the SDM even with ignition in ACCESSORY



Torque to Rotate From Run to Accessory




Non-Deployment Allegations by Model Year Cobalt (22), G5 (1)



A revision to the switch occurred during the 2007 MY to increase the torque to rotate.

- The part number was not changed and the breakpoint is unconfirmed, but is believed to be in early November 2006.
- 4 of the allegations within the 2007 MY are after November 2006.


2005-7 Cobalt/G5 Non Deploy Incidents & Population by MOB



Build date not available for one 2005 vehicle


As of 10/1/13

2005-7 Cobalt / G5 Reports of Airbag Non-Deploy by Model Year & Incident Date



As of 10/1/13

Severity of Injuries: 2005-7 Cobalt / G5 Reports of Airbag Non-Deploy



Severity Summary:

- 7 mild
- 9 moderate
- 2 severe
- 5 fatal

As of 10/1/13

Reports - Potential Key Rotation – Cobalt, G5 and Pursuit

	2005	2006	2007	2008	2009	2010
Airbag Non-Deploy	11	7	5			
Stalling VOQs	12	13	1	1	1	
TREAD Search	56	43	10	1		
Key Insert (Svc. Bulletin)	169	71	6			
Total	248	134	22	2	1	0


- 24 of the 407 total reports are G5 or Pursuit. All others are Cobalt.
- All airbag Non-Deployment reports included vehicles that had left the road surface.

Normalized Report Rate


Model Year	Total Reports	U.S. Population	Reports / 100k Vehicles / Years Exposure
2005	248	140,646	19.6
2006	134	229,231	7.4
2007	22	248,137	1.3




2005-2009 Cobalt VOQs for Potential Ignition off While Driving




2003-9 Ion, HHR VOQs for Potential Ignition off While Driving



2003-9 Ion, Cobalt, HHR, VOQs for Potential Ignition off While Driving



2003-9 Ion, Cobalt, HHR, VOQs for Potential Ignition off While Driving



#05-02-35-007 Information on Inadvertent Turning of Key Cylinder, Loss of Electrical System and No DTCs -

- Issued Nov 2005
- Reissued July 2011 to add the 2007 MY.

Subject: Information on Inadvertent Turning of Key Cylinder, Loss of Electrical System and No DTCs




This bulletin is being revised to add a model year. Please discard Corporate Bulletin Number 05-02-35-007 (Section 02 – Steering).

There is potential for the driver to inadvertently turn off the ignition due to low ignition key cylinder torque/effort.


The concern is more likely to occur if the driver is short and has a large and/or heavy key chain. In these cases, this condition was documented and the driver's knee would contact the key chain while the vehicle was turning and the steering column was adjusted all the way down. This is more likely to happen to a person who is short, as they will have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and should take steps to prevent it – such as removing unessential items from their key chain.

Engineering has come up with an insert for the key ring so that it goes from a "slot" design to a hole design. As a result, the key ring cannot move up and down in the slot any longer – it can only rotate on the hole. In addition, the previous key ring has been replaced with a smaller, 13 mm (0.5 in) design. This will result in the keys not hanging as low as in the past.



Key Insert Claims by Build Month P/N 15842334




MODEL	2005	2006	2007	Total
Cobalt	169	71	6	246
G5			4	4
HHR		35	2	37
ION	51	98	33	182
Pursuit	12	9		21
Solstice		4	1	5
Total	232	217	46	495

Key
Slot vs. Hole
Cobalt



2005 Salvage Yard Cobalt

2008 Salvage Yard Cobalt



- Ignition switch with increased effort passed validation 4/26/06.
- Part number not changed.
- Implementation date is unknown.

- 12 spring coils
- Run to Acc: -7.7 N-cm
- Cap is shorter than observed in MY 07+ and aftermarket switches

- 15 spring coils
- Run to Acc: -22.6 N-cm

EDUARDO RODRIGUEZ
GENERAL MOTORS COMMODITY VALIDATION SIGN-OFF

pg. 1 of 2

Buyer's concurrence on the Seller's completion of validation shall not limit, impair, or otherwise modify Buyer's right to assert any legal or equitable remedy, or relieve Seller of its responsibility to provide conforming goods.

Part Name* GMX 357 Delta Ignition Switch Part Number* 10352423 Suffix/ Release Level* 001
 Shown on Drawing No.* 10392423 / 22873957 Engineering Design Record Change Level* N/A Dated* 27AP04
 Procuring Division* NAO Application/Program* GMX 357 Purchase Order No.* _____
 GM Lead Engineer* Ray DeGiorgio GM Validation Engineer* _____

SUPPLIER MANUFACTURING INFORMATION

Supplier Name* Delphi Mechatronic DUNS Number* 812502961
 Street Address* _____

REASON FOR SUBMISSION*

Initial Submission Resubmission due to Engineering Change(s) Resubmission to correct problems in initial submission

COMMODITY VALIDATION SIGN-OFF REQUIREMENTS*

Specified by Procuring Division in SOR or in separate written request. Page 2 lists more information about the required documentation.

- The Supplier has submitted the required proof of validation completion as specified in SOR Appendix G, Section 4 (i.e., GP-11 ADV or executive letter certifying that commodity is validated).
- All issues that are the responsibility of the Supplier have been classified as "closed" and the resolution of each issue has been confirmed by successful validation. This includes those issues that were identified during development, design validation, or product validation, whether those issues are tracked by GM or by the Supplier.
- All Corrective Action Plans (CAP) that are the responsibility of the Supplier have been classified as "closed."
- The information in the Supplier's issue tracking system has been updated and is consistent with the final resolution of all supplier issues and CAPs.
- The Supplier has completed its final ADV P&R (GM 1829-2) summarizing ADV execution status.
- Supplier's ADV Plan(s) and all specified ADV activities have been completed, including activities required to resolve issues identified during development and validation.
- Supplier has obtained GM approval of the detailed validation results for those requirements for which GM approval was specified in the "Other Validation Requirements" column of the Final VCRI.
- Supplier evaluation reports have been completed for all regulatory requirements for which the Supplier conducted ADV activities to confirm compliance of the commodity.
- Supplier evaluation reports have been completed for those non-regulatory requirements or procedures that were identified in SOR Appendix G, in the Final VCRI, or in writing by the program.
- The Supplier has submitted the commodity models, etc. required for the Virtual Archive.

Yes	<input checked="" type="checkbox"/>	No		
Yes	<input checked="" type="checkbox"/>	No		
Yes	<input checked="" type="checkbox"/>	No		
Yes	<input checked="" type="checkbox"/>	No		
Yes	<input checked="" type="checkbox"/>	No		
Yes		No		Not required by SOR <input checked="" type="checkbox"/>
Yes		No		Not required by SOR <input checked="" type="checkbox"/>
Yes		No		Not required by SOR <input checked="" type="checkbox"/>
Yes		No		Not required by SOR <input checked="" type="checkbox"/>
Yes		No		
Yes		No		

11. Other: _____
 12. Other: _____

Note that the during cycling, 1 amp was applied on the Delta Ignition Sw. This validation was submitted with New PCB correct timings adjusts as Customer required, also New detent plunger (Catara spring/Plunger) was implemented to increase torque force in the switch.

Supplier Name (please print)* Eduardo Rodriguez Title* Present Product Eng Phone No.* _____
 Supplier Authorized Signature* _____ Dated* 4/24/06

GM DECISION: Rejected (see comments below) Re-submit (see comments below) Sign-Off Complete
 GM Name (please print) Ray DeGiorgio Phone No. _____
 GM Authorized Signature* _____ Code: CZ24 Dated: APRIL 26, 2006


Note that the during cycling, 1 amp was applied on the Delta Ignition Sw. This validation was submitted with New PCB correct timings adjusts as Customer required, also New detent plunger (Catara spring/Plunger) was implemented to increase torque force in the switch.

RARIW9G LEFT #3 POTHOLE 25MPH


A1BL 6FAN4822 (18IN/32F/35R)
ELEC DATA, NO DIGITAL FILTER

SDM-30 TOP CASE #7 ACCEL.


TEST DATE:10/03/2013




Torque to Rotate From Run to Accessory



Torque to Rotate From Run to Accessory



2005-7 Cobalt/G5 Non Deploy Incidents & Population by MOB



Build date not available for one 2005 vehicle

As of 10/1/13



Torque Gauge Measurements (Steering Columns from Salvage Yards)

Model Year	Model & VIN	P/N	Cap Size	Off to Acc (N-cm)	Acc to Run (N-cm)	Run to Start (N-cm)	Run to Acc (N-cm)	Acc to Off (N-cm)
2005	Cobalt VIN 1306	10392423	Short	2.8	7.4	50.9	-6.0	-6.7
2005	Cobalt VIN 2380	10392423	Short	3.2	7.8	48.0	-7.8	-8.1
2006	Cobalt VIN 7326	10392423	Short	2.1	7.8	50.9	-7.1	-8.1
2006	Cobalt VIN 6342	10392423	Short	2.1	8.5	50.9	-7.8	-8.5
2007	Cobalt VIN 9561	10392423	Long	3.5	19.8	50.9	-16.2	-16.2
2008	Cobalt VIN 4195	15886190	Long	5.3	19.8	48.0	-22.6	-22.6
2008	Cobalt VIN 0386	15886190	Long	4.9	17.0	48.0	-19.8	-22.6
2009	Cobalt VIN 3438	15886190	Long	3.2	19.8	53.7	-15.5	-15.9

DRAFT Privileged and Confidential
Attorney Work Product

Non-deploys due to Ignition Switch Rotation

2005-7 Cobalt, G5, Pursuit, 2003-2007 Ion, 2006-2007 HHR

	Incident Reports	U.S. Population	IPHTV / Year Exposure
2005-2007 Cobalt	23	618,014	0.47
2005 Cobalt	11	140,646	0.89
2006 Cobalt	7	229,231	0.38
2007 Cobalt	5	248,137	0.29
2006-2007 HHR	0	214,072	0
2003-2007 Ion	2^A	478,986	0.04


^A Incidents can not be confirmed to be due to ignition switch rotation.

SDM Sensor Bounce Anomaly – Safety Recall - Decision June 2002 (approx.. 2 yrs. Exposure)

2000 GMT800 (Safety); 2000 S/T (No field action); 2000 M/L (No field action)

	Incident Reports	Population	IPHTV / Year Exposure
2000 GMT800	9	572,108	0.70
2000 S/T	1	455,500	0.11
2000 M/L	0	96,328	0

Severity of Injuries: 2005-7 Cobalt / G5 Reports of Airbag Non-Deploy



Severity Summary:

- 7 mild
- 9 moderate
- 2 severe
- 5 fatal

As of 10/1/13

Injury Severity Comparison

2000 GMT800 Sensor Bounce: 9 Total (3 mild, 3 moderate, 2 severe, 1 fatal)

Fatal	fatal
Skull & nose fracture, laceration right side of face & mouth. Whiplash. Lost consciousness. Wrist, knee, ankle, and foot injury. 6 days ICU	Severe
Belted - Significant head and chest & lower leg injury.	Severe
Fractured neck vertebrae	moderate
Fractured neck vertebrae. Fractured shoulder	moderate
Concussion, sore shoulder, and chest	moderate
No treatment. Claimed chest injury	mild
Head trauma, bruises - treated at hospital	mild
Broken nose	mild

2005-2007 Cobalt, G5, Pursuit: 23 Total (7 mild, 9 moderate, 2 severe, 5 fatal)

Fatality	Fatal
Fatality	Fatal
Driver & Front Passenger: Fatal	Fatal (2)
Fatality	Fatal
Fatality	Fatal
Traumatic Brain Injury	Severe
Quadriplegic	Severe
Bruising to left side of head, cuts to left knee and back P: Fractured ribs, shoulder blade, cuts, and bruises	Moderate
Unknown Injuries (D) P: Broken neck (w/o paralysis), fractured ribs, sternum, laceration to head, facial bruises	Moderate
Fractured ribs, nose, femur, and ankle	Moderate
Fractured vertebrae and severe ear laceration	Moderate
Kidney damage, left arm fracture, internal bleeding	Moderate
Lost teeth, several stiches in mouth, broken ankle, broken wrist	Moderate
Syncope, concussion, occipital laceration, multiple contusions, seizure disorder	Moderate
Fractured nose & scapula P:fractured leg	Moderate
Severe TBI, Basilar skull fracture, right hip fracture, right sacral fracture	Moderate
Facial FX including: R. Orbital floor, R. Maxillary Sinus, and Bilateral Nasal Bone. Facial laceration & concussion	Mild
Bruised chest area, Bruises on head	Mild
Fractured front teeth and multiple contusions	Mild
Laceration to liver, cut nose, bruised chest, bumps all over, sore left knee	Mild
Laceration to head with scarring	Mild
Facial Laceration and dislocated hip	Mild
Broken nose , broken cheekbone, bruised lung, pain in right elbow	Mild

Non-deploys due to Ignition Switch Rotation

2005-7 Cobalt, G5, Pursuit, 2003-2007 Ion, 2006-2007 HHR

	Incidents Per 100k Vehicles /Year Exposure		
	Cumulative	2005-2008	2009-2013
2005-2007 Cobalt	0.47	0.86	0.20
2005 Cobalt	0.89	1.42	0.45
2006 Cobalt	0.38	0.58	0.28
2007 Cobalt	0.29	0.81	0.09

SDM Sensor Bounce Anomaly – Decision June 2002 (approx. 2 yrs. Exposure)


2000 GMT800 - Safety Recall

2000 S/T - No field action.

	Incident Reports	Population	IPTV / Year Exposure
2000 GMT800	9	572,108	0.70
2000 S/T	1	455,500	0.11
2000 M/L	0	96,328	0


Cost Estimates (w/o Vehicle Attrition)

2005-2007 Cobalt, G5, Pursuit	Ignition Switch Replacement (Build Dates <11/1/06)	2 Key Inserts (all build dates)
778,563 vehicles	\$41.3M	



Replace Switch

P/N 10392423



Add Insert

P/N 15842334

Vehicle scrap/survival rates are at approximately 91% for this population.



From: Brian Stouffer

Sent: Monday, December 02, 2013 8:14 PM

To: [Grejb](#), Gary R

Cc: John Murawa; Mark A Johnson

Subject: Request for PPAP & Quality Plan Data for Chevrolet Cobalt Ignition Switch P/N 10392423

The information you provided on the change to the Cobalt ignition switch plunger and spring has been very helpful.

Today, I gave an update to some of our directors regarding the status of the investigation into 2005-7 Cobalt frontal airbag non-deployments. I was asked to get the actual PPAP data and not just warrants for the switch in 2005 and then when the plunger and spring change was approved in April 2006 (Change Approval Longer Spring & Plunger 57128dat.doc). Specifically, the data for the switch torque testing is requested (see Ignition Switch Torque Requirements.pptx) attached.

In addition to the torque data for PPAP, any KPC data that was taken from the 2005 – 2008 model years is desired. Torque curves are the item of primary interest. Ultimately, any data taken to support the quality plan is desired.

I understand it may take a several days to gather the requested information. That is significant because my last day of work at GM is Wednesday December 4, 2013. I will be on vacation from that point on until my official retirement 2/1/14 (30 years). Another member of my group will be taking over this project. He is John Murawa. I've included him on this e-mail. His contact information is:

From: Greib, Gary R [REDACTED]
Sent: Tuesday, December 10, 2013 7:10 AM
To: John Murawa
Subject: FW: Request for Information Chevrolet Cobalt Ignition Switch P/N 10392423

John – See below and attached. There appears to be some torque testing data in the attached PPAP sign-off. If there are more specifics, please spell-out exactly what you are looking for and I will forward it on to the plant.

Gary R. Greib
Manager, Product Investigations / Patent Agent
Delphi Legal Staff
[REDACTED]

From: Cuervo, Antero
Sent: Monday, December 09, 2013 5:46 PM
To: Greib, Gary R
Cc: Lopez Martinez, Guadalupe; Miller, Lyle D; Villarreal, Mauricio
Subject: FW: Request for Information Chevrolet Cobalt Ignition Switch P/N 10392423

Gary, our PPAP coordinator found the following documentation. It is a newer warrant with some validation data attached. No data related to the original warrant was found.

GENERAL MOTORS COMMODITY VALIDATION SIGN-OFF **

Pg. 1 of 2

Buyer's concurrence on the Seller's completion of validation shall not limit, impair, or otherwise modify
Buyer's right to assert any legal or equitable remedy, or relieve Seller of its responsibility to provide conforming goods.

March 17, 2006

Part Name* GMX001/002 IGNITION SW		Part Number* 15986190	
Shown on Drawing No.* 15986190		Rev 001	
Eng'g Design Record 001		Dated* March 17, 2006	
Change Level*			
Procuring Division* NAC	Application Program* G480021/002	Purchase Order No.* 1336 (JTEKT)	
GM Lead Engineer* Raymond DeGiorgio		GM Validation Engineer* Eugene P. Carnage	
Supplier Resident Engineer: N/A			

SUPPLIER MANUFACTURING INFORMATION

Supplier Name* Delphi Mechatronic Systems DUNS Number* 812502961
 Street Address* [REDACTED]

REASON FOR SUBMISSION*

Initial Submission Re-submission due to Engineering Changes Re-submission to correct problems in initial submission
 EWO # (s) W/O 572658

COMMODITY VALIDATION SIGN-OFF REQUIREMENTS

Specified by Procuring Division in Appendix G2 (or G) and GMN0900 or in separate written request.
 Page 2 lists more information about the required documentation.

	YES	NO	Not Req'd by SOR
1. Supplier has submitted the required 'Proof of Validation Letter' as specified in GMN0900 Section 5.1 and any required regulatory compliance documentation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2. The Supplier has completed execution of their ADV Plan(s) including activities to resolve issues identified during development and validation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3. All ADV issues that are the responsibility of the Supplier have been addressed and classified as 'closed'. This includes those Supplier commodity issues identified during development, design validation, or product validation, validation assurance testing and post-validation audits whether or not those issues are tracked by GM or by the Supplier.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4. The information in the Supplier's issue tracking system has been updated and is consistent with the final resolution of all ADV issues.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5. The Supplier has completed its final ADV PSR (GM1628) which indicates completion of validation to the technical requirements as specified in the Final Technical Specification, approved Engineering Work Order or in writing by GM.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6. All other ADV tasks/deliverables specified in the SOR are complete.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7. If applicable, all regulatory compliance evaluation reports and documentation have been completed and documents requested by GM have been submitted to the Validation Engineer.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
8. If applicable, the Supplier shall have obtained approval of the detailed validation results for those product technical requirements for which GM approval was specified in the 'Other Validation Requirements' column of the Final VGR, in SOR Appendix G2 (or G) or an approved Engineering Work Order.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
9. The Supplier has submitted to the GM CAE Engineer for the commodity the models required for the Virtual Archive Vehicle as specified in the SOR.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
10. Other: Validation for carry over program GMX001 with Resistor value of 1.3 kOhms. Controlling the amount of grease in the PCB assembly	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Explanation of 'NO' answers or comments here: _____

Supplier Name (please print)* Meray Gonzalez Title* Present Product En
 Supplier Authorized Signature* [REDACTED] Phone No* [REDACTED]
Dated* 05/02/07

GM DECISION: Rejected (see comments) Re-submit (see comments) Only Reqs 1 & 5 met (see comments) Sign-Off Complete

GM Validation Engineer Name (please print)* Eugene P. Carnage Phone* [REDACTED]
 GM Validation Engineer Signature* [REDACTED] Date* 3.21.07
 GM Lead Engineer Name* (please print)* Raymond DeGiorgio Phone* [REDACTED]
 GM Lead Engineer Signature* [REDACTED] Date* 3/3/7

Comments: _____

Analysis/Development/Validation Plan & Report (ADV P & R) --GM 1829

SECTION I -- COMMODITY DESCRIPTION PART # 145742 (10000) PART NAME WTS THRT 4000000000 QTY # REVISION LEVEL RELEASE DATES	SECTION II A -- SUPPLIER INFORMATION SUPPLIER NAME DELPHI ELECTRONIC SYSTEMS SUPPLIER CONTACT SOURCE Request People SUPPLIER CONTACT PHONE NUMBER (313) 441-3333 SUPPLIER CONTACT'S MAIL ADDRESS 2800 S. WOODRIDGE BLVD
--	--

SECTION II B -- GM CONTACT INFORMATION/APPROVAL GM CONTACT NAME/PHONE NO. [REDACTED] PHONE NUMBER AND EXT. NO. [REDACTED]	DATE: 2/24/07 BY: [REDACTED]
--	---------------------------------

SECTION III -- ADV PLAN SUMMARY

ITEM #	PROCEDURE #	PROCEDURE TITLE	REQMT #	REQMT TITLE	REGULATORY	REQMT VALUE	RESPON SBLTY	EVALUATION		SAMPLE		TRNG		SAMPLES TESTED			RESULTS	NOTES
								PHASE	METHOD	QTY	TYPE	START	COMP	QTY	TYPE	STAGE		
1	1240020	COMPONENT TECHNICAL SPECIFICATION	3.2.1.3	Voltage Drop	USA	350 mV Max.	DELPHI	PWA	Y	12	F	4560	4561	12	F	Prod.	Met Requirements	
2	1240020	COMPONENT TECHNICAL SPECIFICATION	3.2.1.5	Open Circuit Resistance	USA	30 Mohm Min.	DELPHI	PWA	Y	12	F	4567	4568	12	F	Prod.	Met Requirements	
3	1240020	COMPONENT TECHNICAL SPECIFICATION	3.2.1.8	Isolation Resistance	USA	30 Mohm Min.	DELPHI	PWA	Y	12	F	4567	4568	12	F	Prod.	Met Requirements	
4	1240020	COMPONENT TECHNICAL SPECIFICATION	3.2.2.3	Tensile Characteristics (Torque-Angle)	USA	Adhesion Torque AS to show Backstament (As per Drawing)	DELPHI	PWA	Y	12	F	4567	4568	12	F	Prod.	Did not meet requirements OK 5/12/07 Travel: 45.000 degrees to -45.000 degrees. DUT #2 = -45.367 degrees. DUT #3 = -45.529 degrees. DUT #4 = -45.529 degrees. DUT #7 = -45.439 degrees. DUT #8 = -45.355 degrees. DUT #9 = -45.274 degrees. DUT #11 = -45.257 degrees & DUT #12 = -45.025 degrees. Travel: 11.000 degrees to -11.000 degrees. DUT #2 = -11.545 degrees. DUT #3 = -11.523 degrees. DUT #5 = -11.854 degrees. DUT #7 = -11.855 degrees. DUT #8 = -11.499 degrees. DUT #9 = -12.255 degrees. DUT #11 = -11.484 degrees & DUT #12 = -11.715 degrees. Travel: 32.000 degrees to -32.000 degrees. DUT #8 = -32.150 degrees. Travel: 17.000 degrees to -17.000 degrees. DUT #1 = -17.343 degrees. DUT #2 = -16.133 degrees. DUT #3 = -16.779 degrees. DUT #4 = -17.226 degrees.	

Extension Applied
TABLE CHARACTERISTICS

2005-7 Cobalt, G5, Pursuit, 2003-2007 Ion, 2006-2007 HHR

Condition:

A review of selected Cobalt & G5 frontal crash events indicates some airbag non deploys have occurred where the ignition switch was in accessory or off. The condition appears to be limited to 2005-07 Cobalt & G5 vehicles. The noted field events involve vehicles going off the road and/or hitting smaller objects shortly before a more significant impact.

Questions:

- Why no incidents on Ion or HHR
 - Ion is Class 2 architecture vs GM LAN on Cobalt and HHR
 - Both disable SDM with key off, but Cobalt/HHR will store ignition state & crash record while Ion will not
 - NISM review indicates 2 potential non-deploys for Ion
 - Ion has different column shroud which could affect potential for key interaction
 - Ion customers may be less likely to have the type of crash needed for the condition
 - Ion has different SDM and supplier than Cobalt
 - HHR has more clearance to the driver's knee
- Why no incidents on 2008-10 Cobalt?
 - Ignition switch was revised to have longer plunger and spring to increase effort (confirmed 10/29/13)
 - Part number not changed, so implementation date is unknown (Validation complete 4/26/06). Salvage yard samples included 2007 vehicles with longer plunger (unknown if any had been replaced in service).

Root Cause:

- The hypothesis is that during the off road event the driver's knee is interacting with the keys and/or the mass of the keys is causing the ignition to rotate

Vehicle Population & Incident Rate 2005-2007

Vehicles Sold in US

	<u>2005</u>	<u>2006</u>	<u>2007</u>
Cobalt/G5# Pursuit	140,464	229,231	248,137
Incidents	11	7	5
IPTV/Yrs Exposure	0.0089	0.0039	0.0030
SOP – 1/1/09	8	4	4
IPTV/Yrs Exposure	0.0142	0.0058	0.0081
1/1/09-10/1/13	3	3	1
IPTV/Yrs Exposure	0.0045	0.0028	0.00085

- 2000 GMT800 0.0070 IPTV/yr (approx 2 yrs exposure @ decision June 2002)
- 2000 S/T truck 0.0011 IPTV/yr no field action
 - SDM anomaly may result in no-deploy

Vehicle Population & Incident Rate 2005-2007

Cobalt & G5

Vehicles Sold in US

	<u>2005</u>	<u>2006</u>	<u>2007#</u>
Cobalt/G5# Pursuit	140,464	229,231	248,137

Incidents*	11	7	5
IPTV/Yrs Exposure	0.0089	0.0039	0.0030

(as of 10/1/13)

Incident rate for 2005 is over 2 times higher than 2006 and about 3 times higher than 2007

Combined IPTV/Yrs Exposure 0.0053

*Except for 1 2007 G5, all reports are Cobalt. There is 1 incident reported on a 2008 vehicle. 2008 vehicle had front sensor fault that disabled system prior to crash.

G5 was 2007 start.

Cobalt, Ion & HHR Ignition Switch Measurement

- 5/22/12 44 vehicles in Davison salvage yard
 - Measured torque (Ncm) and force (N) to turn the ignition switch from Run to Accessory.
 - Five of the vehicles had a replacement key, or a key with a hole vs slot (force not measured)

	Model Year								
Model	2003	2004	2005	2006	2007	2008	2009	2010	Grand Total
Cobalt			1	5	5	3	3	1	18
G5					1		1		2
HHR				4	3	2	1	1	11
Ion	2	5	3	1	2				13
Grand Total	2	5	4	10	11	5	5	2	44

Switch Background


- Ion switch original for 2003. For 2005 capacity tooling was needed for Cobalt. The part number is the same, so it is not known what cavities were used for Ion and then for Cobalt. HHR added in 2006
 - A change was initiated in 2006 to implement a new printed circuit board (12861211 Rev 5) and a new detent plunger (741-79378). The taller plunger and spring with more coils completed validation testing 4/24/06. The switch p/n was not changed, so it is unknown when switches with the new content were put into production or service.*

**The change to the plunger and spring was not confirmed until Delphi provided details with that information on 10/29/13*

2003 Ion vs 2007 Cobalt



2005-7 Cobalt / G5 Reports of Airbag Non-Deploy by Model Year & Incident Date




R* = Run but algorithm disabled


As of 10/1/13

Ignition Cylinder Warranty (N100256)


CTS
(Sidebar w/Retainer)




HHR
(Sidebar w/Retainer)



Cobalt
(Sidebar w/Retainer)



07 Saturn ION
(Sidebar w/Retainer)



Vehicle Scrap Rates

<u>AGE</u>	<u>TRUCKS</u> <u>(Full Size</u> <u>Trucks</u> <u>and Vans)</u>	<u>CARS</u> <u>(All</u> <u>others)</u>
1	100%	100%
2	99%	99%
3	99%	99%
4	98%	97%
5	95%	95%
6	94%	93%
7	93%	92%
8	92%	91%
9	92%	89%
10	91%	85%
11	86%	82%
12	79%	76%

**data pulled by RL Polk in March 2012*

2003 Ion vs 2007 Cobalt



Cobalt – Front Airbag Non-Deployment Incidents Per 100K Vehicles Per Years Exposure

