





07/15/2014 15:19





07/01/2012



08/15/2016 11:44

**Jespersion/Robert Artz land, disposal well that was temporarily abandoned well. Paper thin tank collapses spilling oil and saltwater. No visible dike around site that would hold contamination.**



07/29/2014 19:49

Reclamation site of Mike Artz, Antler oil field that shows large area of clean up. Oil Company reports as zero barrel spill. Report remains at that size to date with NDIC. Picture taken July 2013

